

2024 Fall Arrest / Rope Access System
Inspection Report

Collins Square



BRITWAY

Disclaimer

The assessor believed the information contained within this report to be correct at the time of printing. Briteway does not accept responsibility for any consequences arising from the use of the information herein. The report is based on matters that came to the attention of the assessor during the day of the inspection and should not be relied upon as an exhaustive record of all possible risks or hazards that may exist, or potential improvements that can be made. Information on the latest workers compensation / OHS laws can be found at the relevant state Work Cover authority.

An audit has not been conducted on the system/s on this site.

Only items listed in this report have been inspected. Anything found on site that is not in this report is to be reported to Briteway immediately so that they can assess it and add it to the report.

Project Details

Project Name:	CSQ Annual Inspection
Address:	727 Collins Street
Client:	Walker
Client Contact:	Stewart Calder
Certification Date:	17/12/2024
Certification Expiry:	12 Months from the certification date

Briteway Contact Details

Project Manager:

Mitch Morgan

Project Manager Phone Number:

9676 9320

Project Manager Email Address:

info@briteway.com.au

Briteway Address:

4/8 Rocklea Drive, Port Melbourne VIC 3207

Website:

www.briteway.com.au

Understanding AS/NZS 1891.4: Why Your Fall Arrest System Needs Regular Testing

At Briteway, we prioritize your safety and compliance. Our inspections are conducted in line with the AS/NZS 1891.4:2009 standards, which provide guidelines on the selection, use, and maintenance of fall arrest systems across Australia and New Zealand. This standard ensures that all components used in height safety, from anchor points to harnesses, meet rigorous safety requirements to protect workers operating at heights.

Why Is Regular Testing Essential?

1. **Safety Compliance:** AS/NZS 1891.4 mandates routine inspections to identify wear, corrosion, or damage that could compromise the system. This is essential for maintaining a safe working environment for anyone using height safety equipment.
2. **Long-Term Durability:** Over time, environmental exposure can degrade safety components. For instance, peeling powder coatings, as noted in this report, can lead to rust and reduce the integrity of the anchor points. Regular testing identifies these issues early, allowing timely maintenance or replacement.
3. **Legal Accountability:** Compliance with AS/NZS 1891.4 helps clients avoid liability issues, demonstrating a commitment to safety and adherence to industry standards. This not only protects workers but also reduces potential legal and financial risks for the organization.
4. **Manufacturer's Requirements:** Some components have specific installation and maintenance requirements from their manufacturers. For example, improperly installed ladder brackets must be corrected to ensure stability and adherence to both AS/NZS standards and manufacturer specifications.

Why Briteway Recommends Routine Inspections

At Briteway, our inspections don't just tick boxes—they ensure your system is fully compliant and capable of protecting your team. Routine recertification identifies potential hazards, allows for proactive maintenance, and ensures that your height safety system remains in top condition, aligned with the AS/NZS 1891.4 guidelines.

This commitment to inspection and maintenance safeguards both your people and your compliance status, providing peace of mind and adherence to best practices in height safety.

Other Information:



In accordance with AS/NZS 1891.4 all anchorages have been visually inspected for signs of deterioration which might make them unserviceable, together with any other requirements contained in manufacturers' instructions.

The parent structure has also be visually inspected for modifications or deterioration which might lead to loss of anchorage strength.

Drilled-in anchorages such as friction or glued-in anchorages have been proof tested in accordance with Clause 3.1.2(g) as part of each inspection

Each fall-arrest item has had a service label or tag for recording the last date on which it was inspected, unless otherwise noted, the certification period is 12 months from the date on the label.




Any piece of equipment including both personal and permanently installed items, which has been used to arrest a fall or which shows any defect during inspection shall be withdrawn from service immediately and a replacement obtained if necessary. A do not use tag will be placed as an interim measure.

All below listed items have been certified / re-certified in line with the relevant standards and manufacturer specifications. An audit has not been completed on the premises. Any failed items have been tagged out of service.




Approved By: Mitchell Morgan




Testing

				Static Lines		
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
SL1	Surface Mount	Sayfa	21kN - Fall Arrest	Secure/Correct Fixings?: Yes Surrounding Roof in Good Condition?: Yes Free from Visible Signs of Damage?: Yes Load Tested?: NA	Previously failed due to the layout of the static line not being compliant with AS/NZS1891. It is too short and does not provide full coverage to the entire length of the roof. If the user was to access the corner of the roof whilst using the static line and took a fall, there is a high chance that they will suffer a pendulum fall.	FAIL
					image_20241218_133114_459.jpg 	
					image_20241218_133114_463.jpg 	
					image_20241218_133114_464.jpg 	



Static Lines						
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
					<p>image_20241218_1331 14_465.jpg</p> 	
					<p>image_20241218_1331 14_466.jpg</p> 	
					<p>image_20241218_1331 14_475.jpg</p> 	





Anchor Point						
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
AP1	Surface Mount	Sayfa	15kN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	<p>image_20241218_1325 39_776.jpg</p> 	PASS
AP2	Surface Mount	Sayfa				PASS



BRITEWAY

Roof Safety System Inspection Report

Anchor Point




Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
			15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_1332 02_145.jpg 	PASS
AP3	Surface Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	H.jpg 	PASS
AP4	Surface Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_1327 02_635.jpg 	PASS
GS AP1	Surface Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_1406 54_877.jpg 	PASS
GS AP2	Surface Mount	Sayfa				PASS



BRITEWAY

Roof Safety System Inspection Report

Anchor Point





Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
GS AP3	Surface Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_140953_865.jpg 	PASS
L AP1	Surface Mount	Safety Link	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_075907_226.jpg 	PASS
L AP2	Surface Mount	Safety Link	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_075939_153.jpg 	PASS
L AP3	Surface Mount	Safety Link				PASS



BRITEWAY

Roof Safety System Inspection Report

Anchor Point





Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
			15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0802_43_928.jpg 	PASS
L AP4	Surface Mount	Safety Link	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0802_07_205.jpg 	PASS
L AP5	Surface Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0803_28_806.jpg 	PASS
L AP6	Surface Mount	RIS	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0756_53_743.jpg 	PASS
L AP7	Surface Mount	RIS				PASS



BRITEWAY

Roof Safety System Inspection Report

Anchor Point





Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
			15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_075340_633.jpg 	PASS
L AP8	Surface Mount	RIS	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	X.jpg 	PASS
L AP9	Surface Mount	RIS	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_140032_718.jpg 	PASS
L AP10	Surface Mount	RIS	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_074317_269.jpg 	PASS
L AP 11	Surface Mount	Sayfa				PASS



BRITEWAY

Roof Safety System Inspection Report

Anchor Point





Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
			15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0749 30_638.jpg 	
L AP12	Surface Mount	Sayfa	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0800 23_467.jpg 	PASS
L AP13	Surface Mount	Sayfa	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0801 06_563.jpg 	PASS
L AP14	Surface Mount	Sayfa	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	G.jpg 	PASS
L AP15	Surface Mount	Sayfa				PASS



BRITEWAY

Roof Safety System Inspection Report

Anchor Point





Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
			15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_075730_916.jpg 	PASS
L AP16	Surface Mount	Sayfa	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_075440_819.jpg 	PASS
L AP17	Surface Mount	Sayfa	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_074801_235.jpg 	PASS
L AP18	Surface Mount	Sayfa	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	Al.jpg 	PASS
L AP19	Surface Mount	Sayfa				PASS



BRITEWAY




Roof Safety System Inspection Report

Anchor Point

Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
			15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_075819_243.jpg 	
L AP21	Concrete Mount	Sayfa	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets In Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: YES	image_20241217_082539_835.jpg 	PASS
L AP20	Concrete Mount	Sayfa	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets In Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: YES	image_20241217_082830_106.jpg 	PASS
L AP22	Concrete Mount	Sayfa	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets In Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: YES	image_20241217_082314_594.jpg 	PASS
L AP23		Sayfa				PASS







Anchor Point

Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
L AP24	Concrete Mount	Sayfa	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: YES	image_20241217_082049_486.jpg 	PASS
L AP25	Concrete Mount	Sayfa	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: YES	image_20241217_081612_304.jpg 	PASS
L AP26	Concrete Mount	Sayfa	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: YES	image_20241217_081210_642.jpg 	PASS
L AP27		Sayfa				PASS



Anchor Point




Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
	Concrete Mount		15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: YES	image_20241217_0808 47_873.jpg 	PASS
L AP28	Surface Mount	RIS	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0901 41_595.jpg 	PASS
L AP28	Surface Mount	RIS	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_1411 48_333.jpg 	PASS
L AP29	Surface Mount	RIS	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0902 25_664.jpg 	PASS
L AP30	Surface Mount	RIS				PASS



BRITEWAY

Roof Safety System Inspection Report

Anchor Point





Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
L AP31	Surface Mount	RIS	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_085712_456.jpg 	PASS
L AP32	Surface Mount	RIS	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_090350_164.jpg 	PASS
L AP33	Surface Mount	RIS	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_090521_609.jpg 	PASS
L AP34	Surface Mount	RIS				PASS



BRITEWAY

Roof Safety System Inspection Report

Anchor Point





Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
			15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_090550_826.jpg 	PASS
L AP35	Surface Mount	RIS	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_090710_975.jpg 	PASS
L AP36	Surface Mount	RIS	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_090747_170.jpg 	PASS
L AP37	Surface Mount	RIS	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_090855_978.jpg 	PASS
L AP38	Surface Mount	RIS				PASS



BRITEWAY

Roof Safety System Inspection Report

Anchor Point




Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
			15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_091033_198.jpg 	PASS
L AP39	Surface Mount	Sayfa	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_085743_242.jpg 	PASS
L AP40	Surface Mount	Sayfa	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_085913_616.jpg 	PASS
L AP41	Surface Mount	Sayfa	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_085957_680.jpg 	PASS
L AP42	Surface Mount	Sayfa				PASS



BRITEWAY

Roof Safety System Inspection Report

Anchor Point




Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
L AP43	Surface Mount	Sayfa	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0903 15_316.jpg 	PASS
L AP44	Surface Mount	Sayfa	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0906 29_405.jpg 	PASS
L AP45	Surface Mount	Sayfa	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0900 32_988.jpg 	PASS
L AP46	Surface Mount	Sayfa				PASS



BRITEWAY

Roof Safety System Inspection Report

Anchor Point





Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
L AP47	Surface Mount	Sayfa	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_090823_544.jpg 	PASS
L AP48	Surface Mount	Sayfa	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_091001_415.jpg 	PASS
L AP49	Concrete Mount	Sayfa	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: YES	image_20241217_084609_901.jpg 	PASS
L AP50		Sayfa				PASS



BRITEWAY

Roof Safety System Inspection Report

Anchor Point





Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
	Concrete Mount		15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: YES	image_20241217_085055_983.jpg 	PASS
L AP51	Concrete Mount	Sayfa	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: YES	image_20241217_085138_876.jpg 	PASS
L AP54	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_083556_959.jpg 	PASS
L AP55	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_083521_472.jpg 	PASS
L AP56		Other				PASS



BRITEWAY

Roof Safety System Inspection Report

Anchor Point





Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
	Structure Mount		15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_083427_982.jpg 	PASS
L AP57	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_075240_398.jpg 	PASS
L AP58	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: NO Load Tested?: N/A	image_20241217_075140_915.jpg 	PASS
L AP59	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_075050_373.jpg 	PASS
L AP60		Other				PASS



BRITEWAY

Roof Safety System Inspection Report

Anchor Point

Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
	Structure Mount		15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0745 20_609.jpg 	PASS
L AP61	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0743 59_685.jpg 	PASS
L AP62	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0933 04_794.jpg 	PASS
L AP63	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0932 37_816.jpg 	PASS
L AP64		Other				PASS



BRITEWAY

Roof Safety System Inspection Report

Anchor Point





Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
L AP65	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0930 32_440.jpg	PASS
					image_20241217_0923 16_062.jpg	
L AP66	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0922 50_377.jpg	PASS
L AP67	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0922 16_125.jpg	PASS
L AP68		Other				PASS



BRITEWAY

Roof Safety System Inspection Report

Anchor Point





Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
	Structure Mount		15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_092134_142.jpg 	PASS
L AP69	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_092040_637.jpg 	PASS
L AP70	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: YES	image_20241217_091930_180.jpg 	PASS
L AP71	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_091841_642.jpg 	PASS
L AP72		Other				PASS



BRITEWAY

Roof Safety System Inspection Report

Anchor Point




Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
	Structure Mount		15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_091718_831.jpg 	PASS
L AP73	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_091629_869.jpg 	PASS
L AP74	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_091307_405.jpg 	PASS
L AP75	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: YES	image_20241217_085555_092.jpg 	PASS
L AP76		Other				PASS



BRITEWAY

Roof Safety System Inspection Report

Anchor Point





Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
L AP77	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: YES	image_20241217_100043_867.jpg 	PASS
L AP78	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_100108_804.jpg 	PASS
L AP79	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_095817_547.jpg 	PASS
L AP80		Other				PASS



BRITEWAY




Roof Safety System Inspection Report

Anchor Point

Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
	Structure Mount		15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_095749_653.jpg 	PASS
L AP81	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_095552_881.jpg 	PASS
L AP82	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_095519_978.jpg 	PASS
L AP83	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_100342_444.jpg 	PASS
L AP84		Other				PASS







Anchor Point

Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
L AP85	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_100405_887.jpg	PASS
						
L AP86	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_093637_770.jpg	PASS
						
L AP87	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_093852_429.jpg	PASS
						
L AP88		Other				PASS



Anchor Point





Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
	Structure Mount		15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0939 32_234.jpg 	PASS
L AP89	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0942 00_581.jpg 	PASS
L AP90	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0942 34_076.jpg 	PASS
L AP91	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0944 57_826.jpg 	PASS
L AP92		Other				PASS



BRITEWAY

Roof Safety System Inspection Report

Anchor Point





Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
	Structure Mount		15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0945 26_038.jpg 	PASS
L AP93	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0948 03_719.jpg 	PASS
L AP94	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0948 37_141.jpg 	PASS
L AP95	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_0950 17_070.jpg 	PASS
L AP96		Other				PASS



BRITEWAY

Roof Safety System Inspection Report

Anchor Point





Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
	Structure Mount		15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_095051_258.jpg 	PASS
L AP97	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_095119_544.jpg 	PASS
L AP98	Structure Mount	Other	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_083654_708.jpg 	PASS
C AP1	Purlin Mount	Other	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_101936_458.jpg 	PASS
C AP2	Purlin Mount	Other				PASS



BRITEWAY

Roof Safety System Inspection Report

Anchor Point





Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
			15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_102020_008.jpg 	PASS
CAP3	Purlin Mount	Other	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_102048_128.jpg 	PASS
CAP4	Purlin Mount	Other	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_102506_603.jpg 	PASS
CAP5	Purlin Mount	Other	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_102633_575.jpg 	PASS
CAP6	Purlin Mount	Other				PASS



BRITEWAY

Roof Safety System Inspection Report

Anchor Point




Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
			15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_102811_158.jpg 	PASS
CAP7	Purlin Mount	Other	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_102835_858.jpg 	PASS
CAP8	Purlin Mount	Other	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_111634_598.jpg 	PASS
CAP9	Purlin Mount	Other	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_111702_077.jpg 	PASS
CAP10	Purlin Mount	Other				PASS



BRITEWAY

Roof Safety System Inspection Report

Anchor Point


Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
			15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_111734_407.jpg 	PASS
CAP11	Purlin Mount	Other	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_111924_579.jpg 	PASS
CAP12	Purlin Mount	Other	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_111853_194.jpg 	PASS
LAP52	Concrete Mount	Sayfa	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: NO Load Tested?: N/A	image_20241217_095937_201.jpg 	FAIL
LAP53		Sayfa				FAIL






BRITEWAY

Roof Safety System Inspection Report

Anchor Point

Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
	Concrete Mount		15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: NO Load Tested?: N/A	image_20241217_100011_687.jpg 	





Static Lines

Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
H SL1	Surface Mount	Sayfa	21KN - Fall Arrest	Secure/Correct Fixings?: Yes Surrounding Roof in Good Condition?: Yes Free from Visible Signs of Damage?: Yes Load Tested?: NA	<div style="display: flex; justify-content: space-between;"> <div style="width: 30%;"> image_20241220_072533_899.jpg  </div> <div style="width: 30%;"> image_20241220_072747_230.jpg  </div> <div style="width: 30%;"> image_20241220_073450_820.jpg  </div> </div>	PASS



BRITEWAY

Roof Safety System Inspection Report






Static Lines						
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
H SL2	Surface Mount	Sayfa	21kN - Fall Arrest	Secure/Correct Fixings?: Yes Surrounding Roof in Good Condition?: Yes Free from Visible Signs of Damage?: Yes Load Tested?: NA	<div style="display: flex; justify-content: space-between;"> <div style="width: 20%;"> <p>image_20241220_0738_04_946.jpg</p>  </div> <div style="width: 20%;"> <p>image_20241220_0738_04_948.jpg</p>  </div> <div style="width: 20%;"> <p>image_20241220_0738_04_949.jpg</p>  </div> <div style="width: 20%;"> <p>image_20241220_0738_04_951.jpg</p>  </div> </div>	PASS
Anchor Point						
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
L AP1	Surface Mount	Sayfa				PASS



BRITEWAY

Roof Safety System Inspection Report

Anchor Point






Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
			15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_1148_36_366.jpg 	PASS
L AP2	Surface Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_1149_26_354.jpg 	PASS
L AP3	Surface Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	LINKD 15 image_20241218_1150_07_774.jpg 	PASS
L AP5	Surface Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	LINKDAP5 image_20241218_1141_33_731.jpg 	PASS
L AP6	Surface Mount	Sayfa			LINKD AP6 	PASS



BRITEWAY




Roof Safety System Inspection Report

Anchor Point

Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
			15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_114211_607.jpg 	PASS
L AP7	Surface Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	LINKD AP7 image_20241218_114242_023.jpg 	PASS
L AP8	Surface Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	LINKD AP8 image_20241218_114350_754.jpg 	PASS
L AP9	Surface Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	LINKD AP9 image_20241218_114442_247.jpg 	PASS
L AP10	Surface Mount	Sayfa			LINKD AP10 	PASS



Anchor Point

Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
			15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_1145 26_465.jpg 	PASS
L AP11	Surface Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	LIKID AP12 image_20241218_1146 41_984.jpg 	PASS
L AP12	Surface Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_1147 34_173.jpg 	PASS





Static Lines

Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
T1 - SL1	Surface Mount	Sayfa				PASS



BRITEWAY




Roof Safety System Inspection Report

Static Lines						
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
			21kN - Fall Arrest	Secure/Correct Fixings?: Yes Surrounding Roof in Good Condition?: Yes Free from Visible Signs of Damage?: Yes Load Tested?: NA	image_20241217_1329 45_781.jpg 	
					image_20241217_1329 45_782.jpg 	
					image_20241217_1329 45_784.jpg 	
					image_20241217_1329 45_785.jpg 	



BRITEWAY





Roof Safety System Inspection Report

Static Lines						
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
T1 - SL2	Surface Mount	Sayfa	21kN - Fall Arrest	Secure/Correct Fixings?: Yes Surrounding Roof in Good Condition?: Yes Free from Visible Signs of Damage?: Yes Load Tested?: NA	<p>image_20241217_1329_45_786.jpg</p>  <p>image_20241217_1329_45_800.jpg</p>  <p>image_20241217_1339_58_952.jpg</p> 	PASS



BRITEWAY





Roof Safety System Inspection Report

Static Lines							
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result	
					image_20241217_1339 58_994.jpg		
					image_20241217_1339 58_995.jpg		
					image_20241217_1339 58_996.jpg		
					image_20241217_1339 58_997.jpg		



BRITEWAY




Roof Safety System Inspection Report

Static Lines							
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result	
T1 - SL3	Surface Mount	Sayfa			image_20241217_1339 58_999.jpg		
					image_20241217_1339 59_017.jpg		
					image_20241217_1339 59_018.jpg		
					image_20241217_1339 59_019.jpg		
						PASS	



BRITEWAY



Roof Safety System Inspection Report



Static Lines						
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
			21kN - Fall Arrest	Secure/Correct Fixings?: Yes Surrounding Roof in Good Condition?: Yes Free from Visible Signs of Damage?: Yes Load Tested?: NA	image_20241217_1333 31_557.jpg 	
					image_20241217_1333 31_558.jpg 	
					image_20241217_1333 31_561.jpg 	



BRITEWAY





Roof Safety System Inspection Report

Static Lines						
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
					<p>image_20241217_1333 31_562.jpg</p> 	
					<p>image_20241217_1333 31_569.jpg</p> 	

Anchor Point						
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
T1 - AP1	Surface Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	<p>image_20241217_1335 06_936.jpg</p> 	PASS
T1 - AP2	Surface Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	<p>image_20241217_1335 34_339.jpg</p> 	PASS







Anchor Point

Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
T1 - AP3	Surface Mount	Sayfa	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241217_133134_042.jpg 	PASS
T1 - AP4	Surface Mount	Sayfa	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	J.jpg 	PASS
T1 - AP9	Surface Mount	Sayfa	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_130543_764.jpg 	PASS
T1 - AP10	Surface Mount	Sayfa	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_130614_724.jpg 	PASS
T1 - AP11		Sayfa				PASS






Anchor Point

Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
	Concrete Mount		15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: YES	image_20241218_125406_573.jpg 	PASS
T1 - AP12	Concrete Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: YES	image_20241218_125552_453.jpg 	PASS
T1 - AP13	Concrete Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: YES	image_20241218_125013_989.jpg 	PASS
T1 - AP14	Concrete Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: YES	image_20241218_125851_358.jpg 	PASS



BRITEWAY





Roof Safety System Inspection Report

Static Lines						
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
T2 - SL1	Surface Mount	Sayfa	21kN - Fall Arrest	Secure/Correct Fixings?: Yes Surrounding Roof in Good Condition?: Yes Free from Visible Signs of Damage?: Yes Load Tested?: NA	<p>image_20241218_0741_24_360.jpg</p> 	PASS
					<p>image_20241218_0741_24_361.jpg</p> 	
					<p>image_20241218_0741_24_362.jpg</p> 	
T2 - SL2	Surface Mount	Sayfa			<p>image_20241218_0741_24_364.jpg</p> 	PASS







BRITEWAY

Roof Safety System Inspection Report

Static Lines						
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
			21kN - Fall Arrest	Secure/Correct Fixings?: Yes Surrounding Roof in Good Condition?: Yes Free from Visible Signs of Damage?: Yes Load Tested?: NA	<p>image_20241218_0740_44_468.jpg</p> 	
					<p>image_20241218_0740_44_473.jpg</p> 	
					<p>image_20241218_0740_44_474.jpg</p> 	
					<p>image_20241218_0740_44_476.jpg</p> 	



Static Lines						
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
					 image_20241218_0740 44_478.jpg	
					 image_20241218_0740 44_495.jpg	



Anchor Point						
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
T2 - Level 8 - AP1	Concrete Mount	Sayfa	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: YES	 image_20241218_0752 50_864.jpg	PASS
T2 - Level 8 - AP2	Concrete Mount	Sayfa	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: YES	 image_20241218_0757 22_849.jpg	PASS




BRITEWAY

Roof Safety System Inspection Report

Anchor Point

Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
T2 - Level 8 - AP3	Concrete Mount	Sayfa	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: YES	image_20241218_075913_490.jpg 	PASS
T2 - Level 8 - AP4	Concrete Mount	Sayfa	15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: YES	image_20241218_080159_435.jpg 	PASS





Static Lines

Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
T4 - SL1	Surface Mount	Sayfa	21KN - Fall Arrest	Secure/Correct Fixings?: Yes Surrounding Roof in Good Condition?: Yes Free from Visible Signs of Damage?: Yes Load Tested?: NA	image_20241218_085445_990.jpg 	PASS



BRITEWAY





Roof Safety System Inspection Report

Static Lines							
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result	
					image_20241218_0854 45_993.jpg		
					image_20241218_0854 45_994.jpg		
					image_20241218_0854 45_995.jpg		
					image_20241218_0854 45_997.jpg		



BRITEWAY





Roof Safety System Inspection Report

Static Lines							
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result	
T4 - SL2	Surface Mount	Sayfa			image_20241218_0854 46_018.jpg		
					image_20241218_0854 46_019.jpg		
					image_20241218_0854 46_021.jpg		
					image_20241218_0854 46_022.jpg		
						PASS	



BRITEWAY




Roof Safety System Inspection Report

Static Lines						
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
			21kN - Fall Arrest	Secure/Correct Fixings?: Yes Surrounding Roof in Good Condition?: Yes Free from Visible Signs of Damage?: Yes Load Tested?: NA	image_20241218_0916_35_683.jpg 	
					image_20241218_0916_35_684.jpg 	
					image_20241218_0916_35_685.jpg 	
					image_20241218_0916_35_687.jpg 	



BRITEWAY





Roof Safety System Inspection Report

Static Lines							
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result	
T4 - SL3	Surface Mount	Sayfa	21kN - Fall Arrest	Secure/Correct Fixings?: Yes Surrounding Roof in Good Condition?: Yes Free from Visible Signs of Damage?: Yes Load Tested?: NA	image_20241218_0916 35_688.jpg		
					image_20241218_0916 35_696.jpg		
					image_20241218_0906 40_348.jpg		
image_20241218_0906 40_351.jpg							
						PASS	



BRITEWAY





Roof Safety System Inspection Report

Static Lines						
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
					image_20241218_0906 40_352.jpg 	
					image_20241218_0906 40_354.jpg 	
					image_20241218_0906 40_355.jpg 	
					image_20241218_0906 40_386.jpg 	



BRITEWAY




Roof Safety System Inspection Report

Static Lines							
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result	
					image_20241218_0906 40_387.jpg		
					image_20241218_0906 40_388.jpg		
					image_20241218_0906 40_389.jpg		
					image_20241218_0906 40_391.jpg		



BRITEWAY





Roof Safety System Inspection Report

Static Lines						
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
T4 - SL4	Surface Mount	Sayfa	21kN - Fall Arrest	Secure/Correct Fixings?: Yes Surrounding Roof in Good Condition?: Yes Free from Visible Signs of Damage?: Yes Load Tested?: NA	<p>image_20241218_0906_40_413.jpg</p>  <p>image_20241218_0906_40_414.jpg</p>  <p>image_20241218_0859_53_812.jpg</p> 	PASS



BRITEWAY





Roof Safety System Inspection Report

Static Lines						
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
					image_20241218_0859 53_815.jpg 	
					image_20241218_0859 53_817.jpg 	
					image_20241218_0859 53_818.jpg 	
					image_20241218_0859 53_819.jpg 	



BRITEWAY


Roof Safety System Inspection Report



Static Lines							
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result	
					image_20241218_0859 53_851.jpg		
					image_20241218_0859 53_852.jpg		
					image_20241218_0859 53_854.jpg		
					image_20241218_0859 53_855.jpg		



BRITEWAY

Roof Safety System Inspection Report

Static Lines						
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
					image_20241218_085953_889.jpg 	




Anchor Point						
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
T4 - AP1	Surface Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_085553_578.jpg 	PASS
T4 - AP2	Surface Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_090038_535.jpg 	PASS
T4 - AP3	Surface Mount	Sayfa				PASS



BRITEWAY




Roof Safety System Inspection Report

Anchor Point

Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
T4 - AP4	Surface Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_090108_545.jpg	PASS
						
T4 - AP5	Surface Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_084221_539.jpg	PASS
						
T4 - AP6	Surface Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_084257_231.jpg	PASS
						
T4 - AP7	Surface Mount	Sayfa				PASS



Anchor Point

Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
			15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_0845 15_490.jpg 	PASS
T4 - AP8	Surface Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_0843 54_843.jpg 	PASS
T4 - AP9	Surface Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_1227 42_859.jpg 	PASS




Rigid Rails

Serial No. / Part No.	Type	Quantity	Make	Test Readings	Notes	Result
T4 - L21 - R1		1	Sayfa			PASS



BRITEWAY





Roof Safety System Inspection Report

Rigid Rails						
Serial No. / Part No.	Type	Quantity	Make	Test Readings	Notes	Result
T4 - L21 - R2	Rigid Rail - Structure Mount	1	Sayfa	Secure Fixings?: Yes Surrounding Roof in Good Condition?: Yes Free from Visible Signs of Damage?: Yes Load Tested?: No	image_20250120_1143 13_320.jpg	PASS
						
T4 - L21 - R3	Rigid Rail - Structure Mount	1	Sayfa	Secure Fixings?: Yes Surrounding Roof in Good Condition?: Yes Free from Visible Signs of Damage?: Yes Load Tested?: No	image_20250120_1142 00_562.jpg	PASS
						
T4 - L21 - R4	Rigid Rail - Structure Mount	1	Sayfa	Secure Fixings?: Yes Surrounding Roof in Good Condition?: Yes Free from Visible Signs of Damage?: Yes Load Tested?: No	image_20250120_1138 24_682.jpg	PASS
						



BRITEWAY

Roof Safety System Inspection Report

Rigid Rails						
Serial No. / Part No.	Type	Quantity	Make	Test Readings	Notes	Result
T4 - L21 - R5	Rigid Rail - Structure Mount	1	Sayfa	Secure Fixings?: Yes Surrounding Roof in Good Condition?: Yes Free from Visible Signs of Damage?: Yes Load Tested?: No	image_20250120_1139 28_521.jpg 	PASS
					image_20250120_1150 06_828.jpg 	
					image_20250120_1150 06_829.jpg 	
T4 - L21 - R6	Rigid Rail - Structure Mount	1	Sayfa	Secure Fixings?: Yes Surrounding Roof in Good Condition?: Yes Free from Visible Signs of Damage?: Yes Load Tested?: No	image_20250120_1136 50_769.jpg 	PASS
T4 - L21 - R7		1	Sayfa			PASS



BRITEWAY




Roof Safety System Inspection Report

Rigid Rails						
Serial No. / Part No.	Type	Quantity	Make	Test Readings	Notes	Result
T4 - L21 - R8	Rigid Rail - Structure Mount	1	Sayfa	Secure Fixings?: Yes Surrounding Roof in Good Condition?: Yes Free from Visible Signs of Damage?: Yes Load Tested?: No	image_20250120_1137 18_529.jpg	PASS
					image_20250120_1150 45_808.jpg	
					image_20250120_1150 45_809.jpg	
T4 - UHR - R9	Rigid Rail - Structure Mount	1	Sayfa	Secure Fixings?: Yes Surrounding Roof in Good Condition?: Yes Free from Visible Signs of Damage?: Yes Load Tested?: No	image_20250120_1128 49_223.jpg	PASS
		1	Sayfa			PASS



BRITEWAY


Roof Safety System Inspection Report

Rigid Rails						
Serial No. / Part No.	Type	Quantity	Make	Test Readings	Notes	Result
T4 - UHR - R10	Rigid Rail - Structure Mount	1	Sayfa	Secure Fixings?: Yes Surrounding Roof in Good Condition?: Yes Free from Visible Signs of Damage?: Yes Load Tested?: NA	image_20250120_1131 44_164.jpg	
					image_20250120_1131 56_098.jpg	
T4 - UHR - R11	Rigid Rail - Structure Mount	1	Sayfa	Secure Fixings?: Yes Surrounding Roof in Good Condition?: Yes Free from Visible Signs of Damage?: Yes Load Tested?: No	image_20250120_1130 43_552.jpg	
T4 - UHR - R12	Rigid Rail - Structure Mount	1	Sayfa	Secure Fixings?: Yes Surrounding Roof in Good Condition?: Yes Free from Visible Signs of Damage?: Yes Load Tested?: No	image_20250120_1149 33_923.jpg	
		1	Sayfa			PASS




BRITEWAY




Roof Safety System Inspection Report

Rigid Rails						
Serial No. / Part No.	Type	Quantity	Make	Test Readings	Notes	Result
T4 - UHR - R13	Rigid Rail - Structure Mount			Secure Fixings?: Yes Surrounding Roof in Good Condition?: Yes Free from Visible Signs of Damage?: Yes Load Tested?: No	image_20250120_114058_338.jpg 	

Static Lines						
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
T5 - SL1	Structure Mount	Sayfa	21kN - Fall Arrest	Secure/Correct Fixings?: Yes Surrounding Roof in Good Condition?: Yes Free from Visible Signs of Damage?: Yes Load Tested?: NA	image_20241218_143626_538.jpg image_20241218_143626_539.jpg image_20241218_143626_540.jpg	PASS



Static Lines						
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
					image_20241218_143626_542.jpg 	





Anchor Point						
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
GS AP4	Surface Mount		15KN - Fall Arrest	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_143742_012.jpg 	PASS
LNKD13	Surface Mount		15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A		PASS
LNKD14	Surface Mount		15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A		PASS



BRITEWAY




Roof Safety System Inspection Report

Anchor Point

Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
LINKD15	Surface Mount		15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A		PASS
LINKD16	Surface Mount		15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	 image_20241218_115053_923.jpg	PASS
LINKD17	Surface Mount		15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	LINK  image_20241218_115128_949.jpg	PASS
LINKD18	Surface Mount		15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	 image_20241218_115224_334.jpg	PASS
LINKD19	Surface Mount				LINKD 17	PASS



Anchor Point

Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
			15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_1153 31_260.jpg 	PASS
LNKD20	Surface Mount		15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	LNKD 19 image_20241218_1154 10_198.jpg 	PASS
LNKD20	Surface Mount		15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets In Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: N/A	image_20241218_1154 37_345.jpg 	PASS

Anchor Point





Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
TB-AP6		Sayfa				PASS





BRITEWAY



Roof Safety System Inspection Report

Anchor Point


Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
	Concrete Mount		15KN - Fall Arrest	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: YES	image_20241217_111409_226.jpg 	PASS
TB AP 5	Concrete Mount	Sayfa	15KN - Fall Arrest	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: YES	image_20241217_111457_433.jpg 	PASS
TB AP3	Concrete Mount		15KN - Rope Access	Secure Fixings?: YES Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: YES	image_20241217_111938_559.jpg 	PASS
TB AP 4	Concrete Mount	Sayfa	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: YES Free from Visible Signs of Damage?: YES Load Tested?: YES	image_20241217_112241_220.jpg 	PASS
TB AP 1		Sayfa				PASS






Anchor Point						
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
	Concrete Mount			Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: YES	image_20241217_112617_032.jpg 	
TB AP2	Concrete Mount	Sayfa	15KN - Rope Access	Secure Fixings?: N/A Surrounding Roof Sheets in Good Condition?: N/A Free from Visible Signs of Damage?: YES Load Tested?: YES	image_20241217_112940_793.jpg 	PASS

Static Lines						
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
TB SL 01	Concrete Mount	Sayfa	21KN - Fall Arrest	Secure/Correct Fixings?: Yes Surrounding Roof in Good Condition?: Yes Free from Visible Signs of Damage?: Yes Load Tested?: Yes	image_20241217_113313_088.jpg  image_20241217_113313_091.jpg 	PASS







Static Lines						
Serial No. / Part No.	Type	Make	Rating	Test Readings	Notes	Result
					image_20241217_1133 13_093.jpg 	

Needle Arm						
Serial No. / Part No.	Quantity	Make	Rating	Test Readings	Notes	Result
R1		Hi Rise	15kN - Rope Access / Fall Arrest	Free From Damage: Yes All fixing bolts in place?: Yes	image_20241217_1348 35_575.jpg  image_20241217_1348 35_577.jpg  image_20241217_1348 35_578.jpg 	PASS



BRITEWAY





Roof Safety System Inspection Report

Needle Arm							
Serial No. / Part No.	Quantity	Make	Rating	Test Readings	Notes	Result	
R12		Hi Rise			image_20241217_1348 35_579.jpg		
					image_20241217_1348 35_580.jpg		
					image_20241217_1348 35_593.jpg		
					image_20241217_1348 35_594.jpg		
						PASS	





BRITEWAY

Roof Safety System Inspection Report

Needle Arm							
Serial No. / Part No.	Quantity	Make	Rating	Test Readings	Notes	Result	
			15kN - Rope Access / Fall Arrest	Free From Damage: Yes All fixing bolts in place?: Yes	image_20241217_1347 53_883.jpg		
					image_20241217_1347 53_884.jpg		
					image_20241217_1347 53_885.jpg		
					image_20241217_1347 53_887.jpg		



Needle Arm							
Serial No. / Part No.	Quantity	Make	Rating	Test Readings	Notes	Result	
					image_20241217_1347 53_888.jpg		
					image_20241217_1347 53_897.jpg		

Other Information:

In accordance with AS/NZS 1891.4 all anchorages have been visually inspected for signs of deterioration which might make them unserviceable, together with any other requirements contained in manufacturers' instructions.

The parent structure has also be visually inspected for modifications or deterioration which might lead to loss of anchorage strength.

Drilled-in anchorages such as friction or glued-in anchorages have been proof tested in accordance with Clause 3.1.2(g) as part of each inspection

Each fall-arrest item has had a service label or tag for recording the last date on which it was inspected, unless otherwise noted, the certification period is 12 months from the date on the label.

Any piece of equipment including both personal and permanently installed items, which has been used to arrest a fall or which shows any defect during inspection shall be withdrawn from service immediately and a replacement obtained if necessary. A do not use tag will be placed as an interim measure.



BRITEWAY

Roof Safety System Inspection Report

All above listed items have been certified / re-certified in line with the relevant standards and manufacturer specifications. An audit has not been completed on the premises. Any failed items have been tagged out of service.

Approved By: Mitch Morgan






BRITEWAY




Recommended Scope of Works:

Based on the findings of this inspection, the following works are recommended:


1. No further works are required.

Additional Job Photos

-  FALL ARREST ANCHOR POINT
-  ROPE ACCESS ANCHOR POINT
-  STROP



710 Collins Street





Goods Shed	Drawn: RH	Anchor Point	●	Stop	—○	Ladder Bracket	□	Biltasafe – The Experts in Roof Safety T: (03) 8319 0679 F: (03) 8880 0733 M: 0414 588 843 P: 1 Rocklea Drive, Pent Welsburn, 3207
	Design: RH	Static Line	●	●	●	Walkway	▤	
	Review: CB	Guardrail	—	—	—	Roof Access Hatch	▤	
	NTS	Fixed Ladder	▤			No Access	▤	

Verify all dimensions and site measure before commencing work. Do not scale from this drawing. This drawing is copyright and remains the property of Biltasafe and should not be reproduced or copied without the written permission of Biltasafe. Unless Specified this layout is for gutter edge protection only. Skylights are deemed as a fall hazard. Biltasafe suggest skylight covers are used.



<h3>Lantern Building</h3>		Drawn: RH	Anchor Point	●	Strop	—○	
		Design: RH	Static Line	●—●	Strop	—○	
<h3>Lantern Building</h3>		Review: CB	Guardrail	—	Roof Access Hatch	▽	
		NTS	Fixed Ladder	▨	No Access	⊗	
		Ladder Bracket		▢	Walkway		▤
		Roof Access Hatch		▽	No Access		⊗
		Bitesafe – The Experts in Roof Safety T: (03) 8319 0979 F: (03) 8800 0735 M: 0414 540 543 P: Rocklea Drive, Port Melbourne 3207					

Verify all dimensions and site measure before commencing work. Do not scale from this drawing. This drawing is copyright and remains the property of Bitesafe and should not be reproduced or copied without the written permission of Bitesafe. Unless Specified this layout is for gutter edge protection only. Skylights are deemed as a fall hazard. Bitesafe suggest skylight covers are used.




Linked	Drawn: RH	Anchor Point	●	Strop	—○	Ladder Bracket	□	Bitesafe – The Experts in Roof Safety T: (03) 8310 0979 F: (03) 8680 0733 M: 0414 549 843 P: Rocklea Drive, Port Melbourne 3207
	Design: RH	Static Line	●—●		Walkway	▤		
	Review: CB	Guardrail	—		Roof Access Hatch	▤		
	NTS	Fixed Ladder	▤		No Access	▤		

Verify all dimensions and site measure before commencing work. Do not scale from this drawing. This drawing is copyright and remains the property of Bitesafe and should not be reproduced or copied without the written permission of Bitesafe. Unless specified this layout is for gutter edge protection only. Skylights are deemed as a fall hazard. Bitesafe suggest skylight covers are used.




Linked		Drawn: RH	Anchor Point	●	Strop	—○	Ladder Bracket	┌	Bittesafe – The Experts in Roof Safety	
Design: RH	Static Line	●—●	●	●	●	●	Walkway	▤	T: (03) 8319 0979	F: (03) 8680 0733
Review: CB	Guardrail	—	—	—	—	—	Roof Access Hatch	▤	M: 0414 549 943	P: 4 Rocklea Drive, Port Melbourne 3207
NTS	Fixed Ladder	┌	┌	┌	┌	┌	No Access	▤	Verify all dimensions and site measure before commencing work. Do not scale from this drawing. This drawing is copyright and should not be reproduced or copied without the written permission of Bittesafe, unless specified this layout is for gutter edge protection only. Skylights are deemed as a fall hazard. Bittesafe suggest skylight covers are used.	



Tower 1 - Level 18

Drawn: RH	Anchor Point	●	Strop	—○—	Ladder Bracket	□	Biltresafe – The Experts in Roof Safety T: (03) 8319 6979 F: (03) 8890 0733 M: 0414 819 943 P: 3 Fockens Drive, Port Melbourne 3207
Design: RH	Static Line	●—●	Guardrail	—	Walkway	□	
Review: CB	Fixed Ladder	▨	No Access	▨	Roof Access Hatch	▨	
NTS							


Verify all dimensions and site measure before commencing work. Do not scale from this drawing. This drawing is copyright and remains the property of Biltresafe and should not be reproduced or copied without the written permission of Biltresafe. Unless specified this layout is for gutter edge protection only. Skylights are deemed as a fall hazard. Biltresafe suggest skylight covers are used.



Tower 1

Drawn: RH	Anchor Point	●	Stop	○	Ladder Bracket	□	Britesafe – The Experts in Roof Safety T: (03) 8319 8979 F: (03) 8680 0733 M: 0414 549 843 P: 3 Rocklea Drive, Port Melbourne 3207
Design: RH	Static Line	●—●			Walkway	▤	
Review: CB	Guardrail	—			Roof Access Hatch	▣	
NTS	Fixed Ladder	▤			No Access	▣	

Verify all dimensions and site measure before commencing work. Do not scale from this drawing. This drawing is copyright and remains the property of Britesafe and should not be reproduced or copied without the written permission of Britesafe. Unless Specified this layout is for gutter edge protection only. Skylights are deemed as a fall hazard. Britesafe suggest skylight covers are used.




Tower 2





Drawn: RH	Anchor Point	●	Strop	○
Design: RH	Static Line	●	Strop	○
Review: CB	Guardrail	—	Strop	○
NTS	Fixed Ladder	▨	Strop	○
	Ladder Bracket	▭	Strop	○
	Walkway	▨	Strop	○
	Roof Access Hatch	▨	Strop	○
	No Access	▨	Strop	○

BriteSAFE – The Experts in Roof Safety
 T: (03) 8319 0979
 F: (03) 8960 0733
 M: 0414 580 943
 P: 1 Redden Drive, Port Melbourne 3207

Verify all dimensions and site measure before commencing work. Do not scale from this drawing. This drawing is copyright and remains the property of BriteSAFE and should not be reproduced or copied without the written permission of BriteSAFE. Unless specified this layout is for gutter edge protection only. Skylights are deemed as a fall hazard. BriteSAFE suggest skylight covers are used.



- FALL ARREST ANCHOR POINT
- ROPE ACCESS ANCHOR POINT
- STROP








Collins Square Tower
4






Britesafe
The Experts in Roof Safety

- FALL ARREST ANCHOR POINT
- ROPE ACCESS ANCHOR POINT
- STROP




Collins Square Tower
4

Verify all dimensions and site measure before commencing work. Do not scale from this drawing. This drawing is copyright and remains the property of Britesafe and should not be reproduced or copied without the written permission of Britesafe. Unless Specified this layout is for gutter edge protection only. Skylights are deemed as a fall hazard. Britesafe suggest skylight covers are used.



FALL ARREST ANCHOR POINT ROPE ACCESS ANCHOR POINT STROP STATIC LINE	FIXED LADDER UNDER 3.5m FIXED LADDER OVER 3.5m LADDER BRACKET ROOF HATCH
RAPTOR RAIL WALKWAY NO ACCESS	Tower 4 Atrium

Verify all dimensions and site measure before commencing work. Do not scale from this drawing. This drawing is copyright and remains the property of Britesafe and should not be reproduced or copied without the written permission of Britesafe. Unless specified this layout is for gutter edge protection only. Skylights are denoted as a fall hazard. Britesafe suggest skylight covers are used.




Tower 4

Drawn: RH	Anchor Point	●	Strop	—○
Design: RH	Static Line	●—●	Walkway	—□
Review: CB	Guardrail	—	Roof Access Hatch	—△
NTS	Fixed Ladder	—	No Access	—X

Biltesate – The Experts in Roof Safety
 T: (03) 831 9079
 F: (03) 890 0733
 M: 0414 580 843
 P: 1 Redden Drive, Port Melbourne 3207

Verify all dimensions and site measure before commencing work. Do not scale from this drawing. This drawing is copyright and remains the property of Biltesate and should not be reproduced or copied without the written permission of Biltesate. Unless Specified this layout is for gutter edge protection only. Skyjibs are deemed as a fall hazard. Biltesate suggest skyjib covers are used.



Tower 5

Drawn: RH	Anchor Point	●	Stop	○	Ladder Bracket	□	Britesafe – The Experts in Roof Safety T: (03) 8319 0979 F: (03) 8060 0733 M: 0414 549 843 P: 1 Rocklea Drive, Fort Meador, 3207
Design: RH	Static Line	●—●			Walkway	▤	
Review: CB	Guardrail	—			Roof Access Hatch	▣	
NTS	Fixed Ladder	▤			No Access	▣	

Verify all dimensions and site measure before commencing work. Do not scale from this drawing. This drawing is copyright and remains the property of Britesafe and should not be reproduced or copied without the written permission of Britesafe. Unless specified this layout is for gutter edge protection only. Skylights are deemed as a fall hazard. Britesafe suggest skylight covers are used.